

Automatic Water Level Recorder


To identify the relationships between groundwater level, precipitation as well as landslide activity.




Rain Gauge: _to measure the rain fall amount.



4. Borehole Drilling:
for core samples
collection, physical
properties analyses
and installing of
monitoring devices



Borehole Inclinometer: To determine the position of the *slip surface*.



Geophysical Investigations: Two-Dimensional resistivity survey and Seismic Refraction



**Monitoring data collection
from borehole extensometer,
21 June, 2011**



**know-how transfer for
connecting casing pipe for
inclinometer, 13 July, 2011**

Schematic plan of the probable counter-measure for one of the landslide zones

